

Article number: 98 001 00 00

## SWS system programming for up to 30 tapping points

Initial instruction included. System programming is carried out strictly according to on-site conditions. Installation and system functionality must be present and correct (water, cabling and power supply); if not, additional costs will be incurred.



---

### Necessary associated articles

Travel and departure costs per km from Olpe plant      Article no: 98 100 00 00

### Hint